



#222159

~ MOUNTING NOTICE ~

Please note that this Charge Air Cooler may have less mounting points than the unit you are replacing due to an improvement from the OEM Manufacturer. The number of mounting points was reduced to facilitate vibration damping and isolation. This prevents certain stress points and increases the lifecycle of the after cooler. It will replace all earlier OEM mount variations.

