



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220414
Creation Date: 2022-04-14



VOLVO Vehicle Diagnostic Report

License Plate: 21VV002

Manufacturer: VOLVO

Year:

Model: WI

Sub Model: Older electrical system

Engine:

Path: VOLVO>Automatic selection>Control unit>Vehicle (MID144)>Trouble codes

Client:

Phone Number:

VIN: 4V4WC9EH9MN259118

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
MID 144,SID 231,FMI 2	SAE J1939 data link.Data erratic, intermittent, or incorrect First occurrence 2022/4/14 15:22 Last occurrence 2022/4/14 15:31	Active Count:2
MID 144,PID 40,FMI 12	Engine Retarder Switches Status.Faulty device or component First occurrence 2021/9/22 15:41 Last occurrence 2022/4/8 18:10	Inactive Count:2
PSID 200,FMI 9	Data link, MID128.Abnormal update rate First occurrence 2021/9/18 13:40 Last occurrence 2022/4/14 15:22	Active Count:4
PSID 211,FMI 9	Data Link, MID219.Abnormal update rate First occurrence 2021/10/9 06:56 Last occurrence 2022/4/14 15:23	Active Count:3
PSID 207,FMI 9	Data link, MID223.Abnormal update rate	Active Count:2
PSID 205,FMI 9	Data link, MID130.Abnormal update rate First occurrence 2021/10/9 06:56 Last occurrence 2022/4/14 15:23	Active Count:6
PSID 202,FMI 9	Data link, MID140.Abnormal update rate First occurrence 2022/4/14 15:22 Last occurrence 2022/4/14 15:31	Active Count:2
PSID 204,FMI 9	Data Link, MID136.Abnormal update rate First occurrence 2021/9/18 13:40 Last occurrence 2022/4/14 15:31	Active Count:2
PSID 14,FMI 9	DataMax General Error.Abnormal update rate First occurrence 2022/4/14 15:22 Last occurrence 2022/4/14 15:31	Active Count:1
PPID 68,FMI 12	Retarder control position.Faulty device or component First occurrence 2022/4/14 15:23 Last occurrence 2022/4/14 15:31	Inactive Count:2
PSID 230,FMI 9	Critical MSW Error or Improper Shutdown.Abnormal update rate First occurrence 2022/4/14 15:23 Last occurrence 2022/4/14 15:23	Inactive Count:2