



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20221117
Creation Date: 2022-11-17



NAVISTAR Vehicle Diagnostic Report

License Plate: PRINCE

Manufacturer: NAVISTAR

Year:

Model:

Sub Model:

Engine:

Path: NAVISTAR>Auto scan>V126 / VT 275: DLCII I6 [during 2004 to 2006]>Trouble codes

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
221 SID 244,FMI 2	Cruise Power Take Off (PTO) control switch circuit fault	Inactive
325 PID 110,FMI 14	Power reduced matched to cooling system performance *M*	Inactive
323 PID 111,FMI 1	Engine coolant level below warning/critical level	Inactive
321 PID 110,FMI 0	Engine Coolant Temperature (ECT) above warning level	Inactive
626 SID 254,FMI 8	Unexpected reset fault *M*	Inactive
354 SID 27,FMI 6	Variable Geometry Turbo (VGT) under duty cycle	Inactive
353 SID 27,FMI 5	Variable Geometry Turbo (VGT) over duty cycle	Inactive
421 SID 1,FMI 5	Cylinder 1 - low side to high side open	Inactive
422 SID 2,FMI 5	Cylinder 2 - low side to high side open	Inactive
423 SID 3,FMI 5	Cylinder 3 - low side to high side open	Inactive
424 SID 4,FMI 5	Cylinder 4 - low side to high side open	Inactive
425 SID 5,FMI 5	Cylinder 5 - low side to high side open	Inactive



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20221117
Creation Date: 2022-11-17

426 SID 6,FMI 5	Cylinder 6 - low side to high side open	Inactive
533 SID 221,FMI 3	IDM - relay voltage high	Inactive