



Shop:
Tel:
Address:

Report ID: MAXIA20230210
Creation Date: 2023-02-10



Cummins Vehicle Diagnostic Report

License Plate: 14KN100

Manufacturer: Cummins

Year:

Model:

Sub Model:

Engine:

Path: Cummins>Control unit>ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109>Trouble codes

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
DTC:195	Coolant level sensor 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:286	SAE J1939 multiplexing configuration error - out of calibration	Active Lamp: Amber Count: 1