



Shop:
Tel:
Address:

Report ID: MAXIA20230421
Creation Date: 2023-04-21



DETROIT Vehicle Diagnostic Report

License Plate: 08WH250

Manufacturer: DETROIT

Year:

Model:

Sub Model:

Engine:

Path: DETROIT>Auto scan>Motor Control Module EPA07(MCM)>Trouble codes

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
SPN 5396 FMI 0	Engine Oil Pressure (EOP) low	Inactive
SPN 10827 FMI 0	Battery voltage low	Inactive
SPN 4107 FMI 0	Fuel temperature circuit voltage low	Inactive
SPN 38541 FMI 0	Diesel Particulate Filter (DPF) HC absorption warning	Inactive
SPN 37773 FMI 0	Diesel Particulate Filter (DPF) HC absorption high	Inactive
SPN 38029 FMI 0	Diesel Particulate Filter (DPF) HC absorption very high	Active
SPN 1245 FMI 0	Turbo actuator (CAN 3) communication fault	Active
SPN 3076 FMI 0	Camshaft position (CMP) sensor timeout	Inactive
SPN 2504 FMI 0	Exhaust Gas Recirculation (EGR) valve circuit open	Inactive
SPN 1736 FMI 0	Exhaust Gas Recirculation (EGR) valve circuit voltage low	Active
SPN 30395 FMI 0	Turbo actuator - no failsafe mode - motor off	Active