



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20211014
Creation Date: 2021-10-14



2003 FREIGHTLINER Vehicle Diagnostic Report

License Plate: P
Manufacturer: FREIGHTLINER
Year: 2003
Model: FL 112
Sub Model:
Engine:
Path: FREIGHTLINER>Automatic selection>Auto scan>Series MBE EPA98 - EPA04 DDEC>Trouble codes

Client:
Phone Number:
VIN: 1FVMBGCV33HL79047
Mileage:
Color:
Status:

Trouble codes

Codes	Description	Status
SID 248 FMI 2	Data link VCU and PLD - no comm btw VCU and PLD	Inactive Count 1
PID 168 FMI 4	Batt vlt (PLD) - voltage below normal	Inactive Count 1
PID 158 FMI 2	Batt vlt - switched - no match of PLD and VCU vlt (PLD)	Inactive Count 1
PID 84 FMI 3	VSS (VCU) circuit open	Inactive Count 6