
Report ID: MAXIA20230201 Creation Date: 2023-02-01

Client:



License Plate: PRINCE

Manufacturer: Cummins Phone Number:

Year: VIN:
Model: Mileage:
Sub Model: Color:
Engine: Status:

Path: Cummins>Auto scan>ISX12 CM2350 X102/X103/X108/ISX15 CM2350 X101/X104/X109>Trouble codes

Trouble codes

Codes	Description	Status
DTC:143	Engine oil rifle pressure data valid but below normal operating range (moderately severe level)	Active Lamp: Amber Count: 1
DTC:415	Engine oil rifle pressure data valid but below normal operating range (most severe level)	Active Lamp: Red Count: 1
DTC:197	Coolant level data valid but below normal operating range (moderately severe level)	Active Lamp: Amber Count: 1
DTC:6418	Engine brake actuator driver 1 circuit - voltage above normal or shorted to high source	Inactive Lamp: None Count: 272
DTC:5655	Aftertreatment 1 scr conversion efficiency - condition exists	Inactive Lamp: Amber Count: 3