## Dismantle Sheet

12PB027	7 2012	PETERBIL	Т 386				1XPHD49X9CD145046
. <u>.</u>		Fluids Fuel Fuel Coolant Power Stee Freon Brake Fluid Transmissic Differential(s	n 3)	] ] ] ] [		Dismantle R/O Chocked Wheels Desting on Jack Stands Desting on Jack	Locations
Pull Initials  D  D	Hood Assy Radiator Radiator Overflo Condensor Cab	A	Available Available Available Not Posted Not Posted	Location 12 C110 4 IA IR	Tag	COMPLETE, HAS CRACK BY RH HINGS PETERBILT 386 SBA BLUE COMPOSIT POLY TANK, ALUM CORE, DOWNFLOV 36.00 36.00 2.25 PETERBILT 386 RADIATOR PLASTIC	E 63.0
	Cab Control Mod Column Seats Heater Motor Radio L Fuel Tanks	dule A	Not Posted Not Posted Not Posted Not Posted Not Posted Available			100 GAL ALUM ROUND TANK ONLY, RE	EAR FILL PETERBILT 386 100 47
	R Fuel Tanks Air Tank	A	Available  Not Posted	en en		25.0 100 GAL ALUM ROUND TANK ONLY, RE 25.0	AR FILL PETERBILT 386 100 47
	Wiper Motor Engine Fan Starter Alternator Flywheel Steering Pump A/C Compressor	<b>A</b>	Not Posted Available Not Posted Not Posted Not Posted Not Posted Not Posted Not Posted			ISX15, 425HP CUMMINS ISX15 180 Day	Parts and Labor 79474365 425
	Transmission Fr Axle Steering Gear Fr Leaf Spring Rr Axle(s)	A	Available Not Posted Not Posted Not Posted Available	ж. — ж		EATON DSP40 AIR PILOT LOW AIR LE	AF
	Brake Control M Power Divider Carrier Axle Shafts	Α	Not Posted Available Available Not Posted Not Posted	i C		DSP40, 3.42R EATON DSP40 3.42 NO RSP40, 3.42R EATON RSP40 3.42 NO	
Dism	Rr Leaf Spring Fifth Wheel Equipment Wheels(4) pantler Notes: ,,,		Available Not Posted Available	S ~		JOST ANY 7.00 OUTBOARD 34.00 PILOT 22.5 ALUM Classic 2.36" Round H	Hole STEER 10 8.25
Notes:	Front Tires Rear Tires		Not Posted Not Posted				

12PB027	2012 PETERBILT	386				1XPHD49X9CD145046		
	Bumper Assembly, Front	Α	Available	YC		Page 2 of 3 DING & SOME CRACKING ON LH CENTER PETERBILT 386 1 PIECE SBA POLY NO		
	L Fender	Α	Available	YC	$\Box$	PETERBILT 386 BLUE EXTENSION FIBERGLASS		
	R Fender	Α	Available	ye	H	PETERBILT 386 BLUE EXTENSION FIBERGLASS		
	L Skirt	Α	Available	NP		MOUNTS IN FRONT OF BATTERY BOX PETERBILT 386 FRONT 19 242 ULTRACAB		
	L Skirt	Α	Available	my.		MOUNTS BEHIND BATTERY BOX PETERBILT 386 MIDDLE 15 242 ULTRACAB		
	L Skirt	Α	Available	NA		PETERBILT 386 REAR 76 242 ULTRACAB		
	R Skirt	Α	Available	NP		MOUNTS IN FRONT OF BATTERY BOX PETERBILT 386 FRONT 19 242 ULTRACAB		
	R Skirt	Α	Available	~p		MOUNTS BEHIND BATTERY BOX PETERBILT 386 MIDDLE 15 242 ULTRACAB		
	R Skirt	Α	Available	NP		PETERBILT 386 REAR 76 242 ULTRACAB		
	Cab Assembly	Α	Available	Y C		COMPLETE CAB, LESS SLEEPER, PETERBILT 386 AIR CUMMINS ISX		
	Deckplate	Α	Available	ye		COMPLETE ULTRACAB  34.5" X 60" ALUMINUM DECKPLATE PETERBILT 386 34.5 X 60 NO		
	Sleeper	Α	Available	V 6		ALUMINUM  COMPLETE 72" UNIBILT SLEEPER PETERBILT 386 BLUE UNIBILT 72 2		
HI	L Tool Box	Α	Available	Marketty in performance thereby.	H	ALUMINUM TOOL/BATTERY BOX PETERBILT 386 33.5 ALUMINUM		
ĦМ	R Tool Box	Α	Available	16	H	ALUMINUM TOOL/BATTERY BOX PETERBILT 386 33.5 ALUMINUM		
HH	L Cab Exterior Panel	Α	Available	IR	H	PETERBILT 386 UNDER DOOR ULTRACAB FIBERGLASS 33		
HH	R Cab Exterior Panel	Α	Available	A CONTRACTOR OF THE PARTY OF TH	H	PETERBILT 386 UNDER DOOR ULTRACAB FIBERGLASS 33		
ΗM	DEF Tank	Α	Available	1   P	H	POLY DEF TANK PETERBILT 386		
HH	Air Cleaner	Α	Available	NEW RESIDENCE OF THE PROPERTY AND ADDRESS OF THE	H	PETERBILT 386 POLY DONALDSON INTERNAL		
H $H$	Exhaust DPF Assembly	Α		1/2	H	CUMMINS ISX15		
H	Axle Housing (Rear)	Α	Available	N	H	EATON RSP40 AIR PILOT LOW AIR LEAF		
	12/28 Please pull and send to 0			k for customer	to pick			
	L Frame Horn	Α	Available	ےسلر	П	PETERBILT 386		
	R Frame Horn	Α	Available	100 C	П	PETERBILT 386		
	Steering Reservoir/Cooler	Α	Available	20	П	PETERBILT 386 FRAME STEEL/PLASTIC		
$\sqcap$	Windshield Washer Reservoir	Α	Available	16	П	PETERBILT 386 RADIATOR		
	Charge Air Cooler (ATAAC)	Α	Available	21		PETERBILT 386 CUMMINS ISX 30.5 34.5 2		
Notes								

## **Post Dismantle Checklist**

All of these items **must** be completed before a truck is considered finished and a new truck will be brought into the bay for dismantle.

	•	
Review Dismantle Sheet before truck goes out to yard		
ALL fluids drained from truck	En	Parts
ALL batteries/battery cables pulled from truck	gine: IS	Parts Unit
ALL parts marked with correct truck number and put on parts cart	Engine: ISX 425HP	;
Cab cleaned out, parts being stored in cab organized	5HP	
ALL driveline pulled and marked with correct ujoint type	52,0 52,0 2462;	
Wheels/Tires pulled	Trans 000   5209*	
— Fuel and hydraulic tanks pulled	missio	
— Lugnuts/Axlenuts put back on hubs	Transmission: 10 SPD   GVW:	
CRR/PDA bolts put back in housing	SPD	
5 <sup>th</sup> wheel inspected	GVW:	
Scrap cleaned up and thrown away (Iron and Aluminum)	e pant robi	ms A 🕾
ALL parts that need washed moved to wash bay	" Carp	16
Tires dismounted, wheels marked with correct truck number and moved to wash bay	And the second s	
— Parts cart moved to warehouse		
— Floor scrubbed and empty parts cart brought out to bay		
Truck Stock Number 12 PBO27 Dismantler Initials Supervisor	Initials	
Scrap Info		
Stock# 908 918 8013 V4855		
Parts to Pull: Location:		
RH & LHdoor		
. •		
Scrap App Completed? (Yes No. (195		

