



Vander Haags Inc.

7501 E US Hwy 40 Kansas City, MO 64129 816-923-7500 Fax: Work Order: 5-141011

Date: 3/27/2019

Total Price: \$ 0.00

Salesperson: Jeff Tatzko

Mileage:

ENGINE SOLD, FAN TO CLUTCH, WOODEN PALLET

NOTE ANYTHING MISSING OR HOLES IN ENG

Work Order Master Item
Parts Unit

07VV184

2007 VOLVO VNL

4V4NC9TG97N429360

TA Dsl Dismantle & Tear Down	
Expected Hours: 27.00 Labor Detail (Job 252423)	Labor Shop Fee EPA Fee
	Job Total

Labor Total:

Subtotal:	\$ 0.00
Tax:	\$ 0.00
Total:	\$ 0.00

0.00

0.00

0.00

Dismantle Sheet

07	VV18	2007	VOLVO V	/NL			4V4NC9TG97N429360
			Fluids Fuel Engine Coolant Power Ste Freon Brake Flui Transmiss Differentia Fluids Drained	d ion I(s)			Dismantle R/O Chocked Wheels Resting on Jack Stands Cleaned Garbage out of Cab Inspected parts for damage Mark Frame Rail with Stock # Tag Cores Post Deman Pictures
Pull	Initials	Mand Sanu		d Status	Location	Tag	
X	100	Hood Assy	A	Available	HOOD RACK	Ш	COMPLETE, LESS HEADLIGHTS, CHROME ON GRILL IS PEELING, COUPLE OF SPOTS SCRAPED VOLVO VNL SBA RED COMPOSITE 56.0
X	111	Radiator		Not Posted	SCRAP		SOURCE OF OF OTO CONTAINED VOEVO VINE SDANED CONFOSITE SO.
		Radiator Overflov	v Bottle	Not Posted	BERNELL STATE		
X	prh	Condensor		Not Posted	SCRAP		
		Cab		Not Posted			All the state of t
		Cab Control Mod	ule	Not Posted			
		Column		Not Posted			
X	WY.	Seats		Not Posted			
		Heater Motor		Not Posted		Ц	
	(5///	Radio		Not Posted		Ц	
A	pre	Fuel Tanks		Not Posted		Ц	
		Air Tank		Not Posted		Ц	
		Wiper Motor	A			Ц	WIPER MOTOR W/ TRANSMISSION VOLVO VNL
X	gn	Engine		Available	SOLD		CORE, ISX, 400HP, JAKES, 943K CUMMINS ISX As-is No Warranty 79168886
		Need to be in SP I	e to go over wha by April 15th if a	at is needed a at all possible.	nd expected Ext. This will be two	. 713 sepe	e verifying everything before it is shipped from your store. Please have that 7 Dave Patton. rate loads worth of engines. SP Please pull the engines located in both tover to the WH6 facility. Ship On: VHI-Other
		Fan	ago thom in vvi	Not Posted	s can also be bi	C	tover to the write facility. Ship On. VHI-Other
		Starter -		Not Posted	A CONTRACTOR OF THE PARTY OF TH	H	AND DESCRIPTION OF THE PROPERTY OF THE PROPERT
		Alternator		Not Posted		П	
		Flywheel		Not Posted	NOTICE OF STREET, STRE	H	COMPANIES DE CONTROL DE LA PRIMA PRIMA PAR MANDACIDADA DE CONTROL DE LA CONTROL DE LA CONTROL DE LA CONTROL DE
		Steering Pump		Not Posted	LOSS IN COLUMN	П	
		A/C Compressor		Not Posted	7	H	THE RESERVE OF THE PROPERTY OF THE PARTY OF
X	org	Transmission	A	Available	Market Bings	П	FULLER FRO16210B TA-D58-049519
		Fr Axle	A	Available	AND RESIDENCE OF THE PARTY OF T	П	ABS MERITOR FF961 12000 AIR 33 PILOT
X	mi	Steering Gear	STEENS PARTIES	Not Posted		\sqcap	
		Fr Leaf Spring(1)	А	Available	A Control of the Cont	П	VOLVO VNL 4.00 2 32.00 27
		Rr Axle(s)	A	Available	DEALEST HELVE	Ħ	MERITOR RD20145 AIR PILOT VOLVO SPRING
		Brake Control Mod	dule	Not Posted	The second secon	П	
X	m	Power Divider	A	Available	BETS STEEN OF	\Box	MERITOR RD20145 3.58 41 3200F1644
X	PIVI	Carrier	A	Available	3800		MERITOR RR20145 3.58 41 3200S1865
		Axle Shafts(2)	A	Available	SECTION OF THE PARTY OF THE PAR		1152L LONG END MERITOR 3206X1350 3206X1350 41 2.10 42.75
-	Disn	nantler Notes: ,			0		
		Rr Leaf Spring(1)	Α	2 ACCOMMONDATION			VOLVO VNL 2.75 2 24 19
		Fifth Wheel		Not Posted			
		Equipment	3416	Not Posted			
X	pm	Wheels		Not Posted			

Notes:

07VV184	2007 VOLVO VNL					4V4NC9TG97N429360
X	Front Tires		Not Posted	П	295/75R22.5	Page 2 of 3
X	Rear Tires		Not Posted	Н	295/75R22.5	CHOCK SECTION AND ADDRESS OF THE PARTY OF TH
	L Fender	Α	Available	П	VOLVO VNL RED EXTENSION FIBERGL	ASS
	R Fender	A	Available	П	VOLVO VNL RED EXTENSION FIBERGL	
	L Fender, Inner	Α	Available	H	VOLVO VNL	
	R Door Assembly, Front	A	Available		COMPLETE, LESS MIRROR, SOME RUS VNL RED NO	T ON BOTTOM EDGE VOLVO
	Cab Assembly	Α	Available		SHELL, FRO16210B, COMPONENTS SOIL CUMMINS ISX SHELL DAY CAB	LD SEPARATE VOLVO VNL AIR
	Cab Suspension	A	Available		CAB AIR RIDE SUSPENSION VOLVO VN	L AIR DAY CAB FRAME
	L Door Interior Panel	Α	Available		VOLVO VNL GRAY NO	- 14-3-18- V
	Steering Shaft	A	Available	П	VNL STEERING SHAFT VOLVO VNL	
	Dash Assembly	Α	Available		SHELL DASH, STRUCTURE ONLY VOLVI	O VNL CUMMINS ISX AIR
	Dash Panel	A	Available		HEADLIGHT SWITCH W/ VENT VOLVO V PANEL 0 ISX 3	NL HEADLIGHT SWITCH
	Dash Panel	Α			CARGO AND DOME LIGHT, 3 EMPTY VO ISX 2	LVO VNL SWITCH PANEL 0
	Dash Panel	A	Available		TRAC LOCK, 6 EMPTY VOLVO VNL SWI	TCH PANEL 0 ISX 1
	Dash Panel	Α	Available		EXHAUST BRAKE, 5 EMPTY VOLVO VNL	SWITCH PANEL 0 ISX 4
X	Instrument Cluster	A	Available WAREHOUSE		VOLVO VNL 10 INSTRUMENT CLUSTER	ISX
X	Air Transfer Tube	A	Available CAB		AIR CLEANER TO TURBO VOLVO OTHER	R CUMMINS ISX POLY
X //VT	Air Cleaner	A	Available CAB		MOUNTS TO CAB VOLVO VNL 15 POLY	DONALDSON INTERNAL
	Exhaust Bracket	A	Available		FRAME MOUNTED STACK BRACKET W/ MOUNT VOLVO VNL STEEL FRAME	CROSSOVER ROD AND
	Axie Housing (Rear)	A	Available		MERITOR RR20145 AIR PILOT VOLVO S	PRING
	Crossmember	Α	Available		VOLVO VNL MIDDLE STEEL	
	Crossmember	A	Available	\Box	VOLVO VNL MID REAR STEEL	-300
	Crossmember	Α	Available	П	VOLVO VNL REAR STEEL	
	Frame	A	Available		INFORMATION ONLY MISC MANUFACTU	RER ANY 10.50 0.2500 3.500
	Steering Reservoir/Cooler	Α	Available	П	VOLVO VNL FRAME PLASTIC	and the second s
	Heater & AC Temperature Co	A	Available	П	3 KNOB, 2 BUTTON VOLVO VNL	Carried Control of the Control of th
	Electrical Misc. Parts	Α	Available	n	ROAD RELAY 4 (CUMMINS ISX) VOLVO V	/NL
	Truck Equipment, Chain Holde	A	Available	H	STEEL CHAIN HOLDER	Code of the Code o
	Accessory Fender	Α	Available	П	SET OF (2) QUARTER POLY SMOOTH	AND REAL PROPERTY.

SPECIAL INVENTORY / DISMANTLE INSTRUCTIONS

Instrument Cluster

VOLVO VNL - Pull cluster out , get pictures of the backside , update the part number in the part record - number in the warehouse.



Example SKU: 24642768

Notes:

Post Dismantle Checklist

All of these items must be completed before a truck is considered finished and a new truck will be brought into the bay for dismantle.

 Review Dismantle Sheet before truck 	goes out to yard	
ALL fluids drained from truck		
ALL batteries/battery cables pulled from the company of the c	rom truck	
— ALL parts marked with correct truck n	number and put on parts cart	
Cab cleaned out, parts being stored in	n cab organized	
ALL driveline pulled and marked with	correct ujoint type	
— Wheels/Tires pulled		
 Fuel and hydraulic tanks pulled 		
 Lugnuts/Axlenuts put back on hubs 		
 CRR/PDA bolts put back in housing 		
— 5 th wheel inspected		
Scrap cleaned up and thrown away (In	on and Aluminum)	
— ALL parts that need washed moved to	wash bay	1
Tires dismounted, wheels marked with	h correct truck number and moved	to wash bay
 Parts cart moved to warehouse 		
Floor scrubbed and empty parts cart b	prought out to bay	01
Truck Stock Number	Dismantler Initials PM	Supervisor Initials
	Scrap Info	•
Stock#		
Parts to Pull:	Location:	
	Location.	
		
Scrap App Completed? Yes No		