



Vander Haags Inc.

7501 E US Hwy 40 Kansas City, MO 64129 816-923-7500 Fax: Work Order: 5-140988

3/26/2019

Total Price: \$ 0.00

Salesperson: Jeff Tatzko

Mileage:

Date:

ENGINE SOLD, FAN TO CLUTCH, WOOD PALLET

NOTE ANY MISSING PARTS AND HOLES LET JEFF KNOW

Work Order Master Item

Parts Unit

07VV173

2007 VOLVO VNL

4V4NC9TJ77N446489

TA Dsl

Dismantle & Tear Down

Expected Hours: 27.00

Labor Detail (Job 252375)

Labor Shop Fee EPA Fee 0.00 0.00 0.00

Job Total

0.00

Labor Total:

Subtotal: Tax: 0.00

Total:

\$

0.00

Dismantle Sheet 4V4NC9TJ77N446489 2007 VOLVO VNL 07VV173 Fluids □ Dismantle R/O □ Chocked Wheels ☑ Engine □ Resting on Jack Stands Coolant ☐ Cleaned Garbage out of Cab ower Steering ☐ Inspected parts for damage Freon ☐ Mark Frame Rail with Stock # Brake Fluid □ Tag Cores fransmission ☐ Post Deman Pictures Differential(s) Fluids Drained by Pull Initials Cnd Status Location Tag COMPLETE, LESS HOOD HINGE VOLVO VNL SBA WHITE COMPOSITE A Available K4A09K0 Hood Assy 56.0 <dap> Picked Up (24714970) by Michael Prickett 2018-12-28 16:51:53 </dap> 12/27 - Called Kale and let him know his hood is ready for pick up. He said he will send someone to pick up tomorrow. 12/27 - PULL HOOD HINGE WITH HOOD PLEASE, KALE CALLED, NEEDS HOOD PULLED, CALL WHEN READY AT 816-651-9316 Ship On: Get Ready for Pickup Not Posted SCRAP VOLVO VNL RADIATOR PLASTIC Radiator Overflow Bottle Available CAB Condensor Not Posted SCRAP Cab Not Posted Not Posted Cab Control Module FOOT OPERATED VOLVO VNL YES MANUAL YES YES Column Available Not Posted Seats Heater Motor Not Posted Available USB CHARGING PORT VOLVO VNL NO YES NO CD PLAYER Radio Fuel Tanks Not Posted Not Posted Air Tank Available WIPER MOTOR W/ TRANSMISSION VOLVO VNL Wiper Motor Engine Available CORE, CUMMINS, 475HP, UNKNOWN FAILURE CUMMINS ISX As-is No Warranty CPL 8519 3682990 475 Before starting on this order, Please designate one person who will be verifying everything before it is shipped from your store. Please have that person contact me to go over what is needed and expected Ext. 7137 Dave Patton. Need to be in SP by April 15th if at all possible. This will be two seperate loads worth of engines. SP Please pull the engines located in both WH4-WH5 and stage them in WH6, Brake shoes can also be brought over to the WH6 facility. Ship On: VHI-Other Fan Not Posted Not Posted Starter Alternator Not Posted Flywheel Not Posted Steering Pump Not Posted A/C Compressor Not Posted Transmission Available FULLER FRO16210C TAD60048793 UNSURE ABOUT MODEL, TRUCK IS TOO LOW TO GROUND TO Fr Axle Available INSPECT, WILL INSPECT AND UPDATE AT DISMANTLE PILOT Dismantler Notes: LET INVENTORY TECHNICIAN KNOW TO COME ADD DETIALS TO THIS STEER AXLE IF IT GOES THROUGH DISMANTLE Steering Gear Not Posted Fr Leaf Spring(1) Available VOLVO VNL 4.00 1 30.00 27 Available MERITOR RD20145 AIR PILOT VOLVO AIR Rr Axle(s)

Not Posted

Notes:

Brake Control Module

X	10/1 h	Power Divider	A	Available		MERITOR RD20145 3.58 41 NO 3200-F-1644
X	VV	Carrier	Α	Available	П	MERITOR RR20145 3.58 41 NO 3200-S-1856
	-	Axle Shafts(2)	Α	Available	Ħ	1152L - long MERITOR 3206X1350 1152L 41 2.10 43.01
	Disn	nantler Notes: ,		THE RESERVE THE PROPERTY OF THE PARTY OF THE	_	NA SERVICE OF THE SER
		Rr Leaf Spring(1)	Α	Available		VOLVO Z SPRING VOLVO VNL 2.75 2
Ti		Fifth Wheel		Not Posted	П	
		Equipment		Not Posted		
X	POM	Wheels(1)	A	Available		PILOT 22.5 ALUM Classic 2.5" Round Hole OUTSIDE REAR 10 8.25
X		Front Tires	_	Not Posted		22.5 295 75
X	TT	Rear Tires		Not Posted		22.5 295 75
		L Cowl	Α	Available		VOLVO VNL CAB COMPOSITE WHITE
		R Door Mirror	В	Available		UPPER FRONT DOOR MOUNT HAS SMALL CRACK, STILL STURDY. COMES WITH UPPER DOOR MIRROR VOLVO VNL POLY YES YES
X	n	L Skirt	A	Available CAB		VOLVO VNL FRONT 220 WHITE
X	VIV	L Skirt	A	Available CAB		CENTER VOLVO VNL CENTER 47 220
X		R Skirt	A	Available CAB		VOLVO VNL CENTER 47
		Cab Assembly	A	Available		SHELL CAB, COMPONENTS SOLD SEPARATE, FRO15210C VOLVO VNL AIR CUMMINS ISX SHELL MID ROOF
		R Fairing (Side)	Α	Available		LESS BRACKETS , NO BRACKETS VOLVO VNL WHITE 15.00 23.75 UPPER
		L Grab Handle	A	Available		25.25" GRAB HANDLE VOLVO VNL FAIRING ALUMINUM 25.25
		L Sleeper Door	Α	Available		VOLVO VNL LOWER 23.00 32 61 MID ROOF
		R Sleeper Door	A	Available		VOLVO VNL LOWER 23.00 32 61 MIDROOF
		L Sleeper Cabinets	Α	Available		VOLVO VNL UPPER
		L Door Interior Panel	A	Available		VOLVO VNL GRAY NO
		R Door Interior Panel	Α	Available		VOLVO VNL GRAY YES
	A)	Dash Assembly	A	Available		SHELL DASH , STRUCTURE ONLY VOLVO VNL CUMMINS ISX AIR MANUAL
X		Instrument Cluster	A	Available WAREHOUSE		VOLVO VNL 10 INSTRUMENT CLUSTER ISX
		Air Cleaner	A	Available		VOLVO VNL 15 POLY DONALDSON INTERNAL
		L Fuel Filter Base	Α	Available K2A04A4		MISC, ANY ADD ON FILTER HOUSING WITH BRACKET CUMMINS ISX
		Axle Housing (Rear)	A	Available		MERITOR RR20145 AIR PILOT VOLVO AIR
		Crossmember	Α	Available		REAR MOST CROSSMEMBER / END CAP VOLVO VNL REAR STEEL
		Frame	A	Available		for information only MISC MANUFACTURER ANY 11.75 0.7500 3.500 no
		Windshield Washer Reservoir	A	Available		VOLVO VNL FRAME
		Heater & AC Temperature Co	A	Available		3 KNOB, 2 BUTTON VOLVO VNL

SPECIAL INVENTORY / DISMANTLE INSTRUCTIONS

Instrument Cluster

VOLVO VNL - Pull cluşter out, get pictures of the backside, update the part number in the part record - number in the warehouse.



Example SKU: 24642768

Notes:

Post Dismantle Checklist

of these tems must be completed before a tru y for dismantle	uck is considered finished and	a new truck will be brought into the
Review Dismantle Sheet before truck goe	es out to yard	12
ALL fluids drained from truck		
AVL batteries/battery cables pulled from	n truck	
ALL parts marked with correct truck num		
Cab cleaned out, parts being stored in ca		
ALL driveline pulled and marked with cor	rrect ujoint type	
Wheels/Tires pulled		
Fuel and hydraulic tanks pulled		
Lugnuts/Axlenuts put back on hubs		4
CRR/PDA bolts put back in housing		B
— 5 th wheel inspected		
Scrap cleaned up and thrown away (Iron	and Aluminum)	
ALL parts that need washed moved to wa	ash bay	
Tires dismounted, wheels marked with co	orrect truck number and mov	red to wash bay
Parts cart moved to warehouse		
Floor scrubbed and empty parts cart broad	ught out to bay	
Truck Stock Number 07 VV 173	Dismantler Initials	Supervisor Initials
	Scrap Info	
Stock#		
Parts to Pull:	Location:	
	-	
Scrap App Completed? Yes No		
The second secon		