



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20210921
Creation Date: 2021-09-21



CATERPILLAR Vehicle Diagnostic Report

License Plate: 2508948-3

Manufacturer: CATERPILLAR

Year:

Model:

Sub Model:

Engine:

Path: CATERPILLAR>Auto scan>C15 truck>ECU information>

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

ECU information

Vehicle Type	C15 truck
Vehicle ID	852991N
Engine S/N	BXS35570
ECM S/N	24546040JJ
Personality Module P/N	3054516-00
Personality Module Release Date	DEC06
Personality Module Code	42
ECM Date/Time	2021/9/21 14:55:35