



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20210921
Creation Date: 2021-09-21



CATERPILLAR Vehicle Diagnostic Report

License Plate: 2508948-5

Manufacturer: CATERPILLAR

Year:

Model:

Sub Model:

Engine:

Path: CATERPILLAR>Auto scan>C15 truck>Trouble codes>

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
284-6	Engine coolant diverter current high (98)	Current