



Repair Shop:  
Phone Number:  
Address:

Report Number: MAXIA20211116  
Creation Date: 2021-11-16



## CATERPILLAR Vehicle Diagnostic Report

License Plate: GGGGHH

Manufacturer: CATERPILLAR

Year:

Model:

Sub Model:

Engine:

Path: CATERPILLAR>Auto scan>C-10 truck>Trouble codes

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

### Trouble codes

| Codes  | Description                       | Status  |
|--------|-----------------------------------|---------|
| 231-12 | SAE J1939 device not responding   | Current |
| 111-2  | Coolant level signal invalid (12) | Current |