



Repair Shop:  
Phone Number:  
Address:

Report Number: MAXIA20211117  
Creation Date: 2021-11-17



## HD OBD Vehicle Diagnostic Report

License Plate: DRGTRT

Manufacturer: HD OBD

Year:

Model: SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>Live data

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

### Engine #1 -- Pressure

NO.	Name	Value	Unit
1	Engine fuel delivery pressure	89.92	psi
2	Engine oil pressure 1	71.36	psi
3	Barometric pressure	14.29	psi
4	Aftertreatment 1 diesel particulate filter intake pressure (use SPN 3609)	14.79	psi
5	Engine intake manifold #1 pressure	0.00	psi
6	Engine intake air pressure	12.18	psi
7	Engine coolant filter differential pressure	0.00	psi