



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220110
Creation Date: 2022-01-10



HD OBD Vehicle Diagnostic Report

License Plate: JV

Manufacturer: HD OBD

Year:

Model: SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>Live data

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Engine #1 -- ALL

NO.	Name	Value	Unit
1	Engine total hours of operation	9927.75	h
2	Engine rated power	373.0	kW