ANNUAL VEHICLE INSPECTION REPORT

HDA TRUCK PRIDE
TruckServiceExperts®

VEHICLE HISTORY RECORD	
REPORT NUMBER	FLEET UNIT NUMBER
	13M1005
DATE	

MOTOR CARRIER OPERATOR	INSPECTOR'S NAME (PRINT OR TYPE): Alfredo Palacios
ADDRESS	THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19. ☑ YES
CITY, STATE, ZIP CODE	VEHICLE IDENTIFICATION (✓ AND COMPLETE) ☐ LIC. PLATE NO. ☑ VIN ☐ OTHER: 1VF813E4DA000038
VEHICLE TYPE ☐ TRACTOR ☐ TRAILER ☐ TRUCK ☐ BUS ☑ (OTHER)	INSPECTION AGENCY/LOCATION (OPTIONAL)

VEHICLE COMPONENTS INSPECTED

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			1. BRAKE SYSTEM
	✓		a. Service Brakes
			b. Parking Brake System
✓			c. Brake Drums or Rotors
			d. Brake Hose
NA			e. Brake Tubing
✓			f. Low Pressure Warning Device
✓			g. Tractor Protection Valve
✓			h. Air Compressor
NA			i. Electric Brakes
NA			j. Hydraulic Brakes
NA			k. Vacuum Systems
✓			l. Antilock Brake System
✓			m. Automatic Brake Adjusters
✓			**2. COUPLING DEVICES**
NA			a. Fifth Wheels
NA			b. Pintle Hooks
✓			c. Drawbar/Towbar Eye
	✓		d. Drawbar/Towbar Tongue
✓			e. Safety Devices
			f. Saddle-Mounts
✓			**3. EXHAUST SYSTEM**
NA			a. No leaks forward of/ directly below the driver/ sleeper compartment.
✓			b. Bus: No leaking/ discharging in violation of standard.
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.
✓			**4. FUEL SYSTEM**
✓			a. No visible leak.
✓			b. Fuel Tank Filler Cap
			c. Fuel tank securely attached.
✓			**5. LIGHTING DEVICES**
			All required lights/reflectors operable.

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			6. SAFE LOADING
NA			a. Vehicle parts, load, dunnage, spare tire, etc., secured.
✓			b. Front End Structure
NA			c. Intermodal Container Securement Devices
	✓		**7. STEERING MECHANISM**
✓			a. Steering Wheel Free Play
✓			b. Steering Column
✓			c. Front Axle Beam/All Other Steering Components
✓			d. Steering Gear Box
✓			e. Pitman Arm
✓			f. Power Steering
	✓		g. Ball and Socket Joints
✓			h. Tie Rods and Drag Links
✓			i. Nuts
✓			j. Steering System
	✓		**8. SUSPENSION**
✓			a. Axle Positioning Parts
✓			b. Spring Assembly
✓			c. Torque, Radius or Tracking Components
	✓		**9. FRAME**
✓			a. Frame Members
✓			b. Tire and Wheel Clearance
NA			c. Adjustable Axle Assemblies (Sliding Subframes)
	✓		**10. TIRES**
✓			a. Steer-Axle Tires
✓			b. All Other Tires
NA			c. Speed-Restricted Tires
	✓		**11. WHEELS AND RIMS**
NA			a. Lock or Side Ring
✓			b. Wheels and Rims
✓			c. Fasteners
✓			d. Welds

OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			12. WINDSHIELD GLAZING
✓			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			13. WINDSHIELD WIPERS
✓			No missing, damaged, or inoperable wipers.
			14. MOTORCOACH SEATS
✓			Seats securely fastened to the vehicle structure.
			15. REAR IMPACT GUARD
✓			In place, securely attached, proper size, proper placement (see 393.86).
			16. OTHER
			List any other condition(s) which may prevent safe operation of this vehicle.

INSTRUCTIONS: MARK COLUMN ENTRIES TO VERIFY INSPECTION: ✓ OK, X NEEDS REPAIR, NA IF ITEMS DO NOT APPLY, _____ REPAIRED DATE

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN