



Shop:
Tel:
Address:

Report ID: MAXIA20220913
Creation Date: 2022-09-13



HD OBD Vehicle Diagnostic Report

License Plate: 09WH173

Manufacturer: HD OBD

Year:

Model: SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>DTC&FFD

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
SPN 3509,FMI 3	Sensor supply voltage 1 Voltage above normal, or shorted to high source	Engine #1 Active Count : 1
SPN 1172,FMI 3	Engine turbocharger 1 compressor intake temperature Voltage above normal, or shorted to high source	Engine #1 Active Count : 1