



Shop:
Tel:
Address:

Report ID: MAXIA20221021
Creation Date: 2022-10-21



Cummins Vehicle Diagnostic Report

License Plate: MB

Manufacturer: Cummins

Year:

Model:

Sub Model:

Engine:

Path: Cummins>Auto scan>X15 CM2350 X114B/X116B>Live data

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

X15 CM2350 X114B/X116B

NO.	Name	Value	Unit
1	ECM distance	448361.49	miles
2	Engine Oil Pressure	24.53	psi
3	Engine coolant temperature	190.40	°F
4	Engine hours	8624:41:39	H:M:S
5	Engine speed	1599	rpm