



Shop:
Tel:
Address:

Report ID: MAXIA20221024
Creation Date: 2022-10-24



Cummins Vehicle Diagnostic Report

License Plate: MB
Manufacturer: Cummins
Year:
Model:
Sub Model:
Engine:
Path: Cummins>Auto scan>X15 CM2350 X114B/X116B>Trouble codes

Client:
Phone Number:
VIN:
Mileage:
Color:
Status:

Trouble codes

Codes	Description	Status
DTC:1117	Power supply lost with ignition ON - data erratic, intermittent or incorrect	Active Lamp: None Count: 1
DTC:3563	Aftertreatment Diesel Exhaust Fluid (DEF) line heater relay voltage below normal or short to low voltage	Active Lamp: Amber Count: 1
DTC:1683	Aftertreatment 1 Diesel Exhaust Fluid (DEF) tank heater voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3558	Aftertreatment 1 Diesel Exhaust Fluid (DEF) dosing unit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3237	Aftertreatment 1 Diesel Exhaust Fluid (DEF) line heater 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3239	Aftertreatment 1 Diesel Exhaust Fluid (DEF) line heater 2 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3422	Aftertreatment Diesel Exhaust Fluid (DEF) line heater 3 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:3567	Aftertreatment Diesel Exhaust Fluid (DEF) dosing valve current below normal or circuit open	Active Lamp: Amber Count: 1
DTC:1881	Aftertreatment Diesel Particulate Filter (DPF) Differential Pressure Sensor (DPS) circuit voltage below normal or short to low voltage	Active Lamp: Amber Count: 1
DTC:3134	Aftertreatment 1 Diesel Particulate Filter (DPF) outlet pressure sensor circuit voltage below normal or short to low voltage	Active Lamp: Amber Count: 1
DTC:3572	Aftertreatment 1 Diesel Exhaust Fluid (DEF) pressure sensor voltage below normal or short to low voltage	Active Lamp: Amber Count: 1
DTC:1845	Water In Fuel (WIF) indicator sensor circuit voltage above normal or short to high voltage	Active Lamp: Maintenance Count: 1



Shop:
Tel:
Address:

Report ID: MAXIA20221024
Creation Date: 2022-10-24



DTC:249	Ambient Air Temperature (AAT) sensor 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:195	Coolant level sensor 1 circuit voltage above normal or short to high voltage	Active Lamp: Amber Count: 1
DTC:285	SAE J1939 multiplexing PGN time-out error - update rate abnormal	Active Lamp: Amber Count: 1
DTC:3232	Aftertreatment 1 inlet Nitrogen Oxide (NOx) sensor update rate abnormal	Active Lamp: Amber Count: 1
DTC:2771	Aftertreatment 1 outlet Nitrogen Oxide (NOx) sensor update rate abnormal	Active Lamp: Amber Count: 1
DTC:3328	Transmission Output Shaft Speed (OSS) update rate abnormal	Active Lamp: Amber Count: 1
DTC:3526	Wheel-based vehicle speed update rate abnormal	Active Lamp: Amber Count: 1
DTC:3868	Aftertreatment Diesel Exhaust Fluid (DEF) quality update rate abnormal	Active Lamp: Amber Count: 1
DTC:6339	Fuel level 1 - abnormal update rate	Active Lamp: Amber Count: 1
DTC:4151	Aftertreatment Diesel Particulate Filter (DPF) temperature sensor module update rate abnormal	Active Lamp: Amber Count: 1
DTC:6688	Aftertreatment 1 particulate sensor - abnormal update rate	Active Lamp: Amber Count: 1
DTC:4677	Aftertreatment 1 Diesel Exhaust Fluid (DEF) tank level update rate abnormal	Active Lamp: Amber Count: 1
DTC:4572	Aftertreatment 1 Diesel Exhaust Fluid (DEF) tank temperature update rate abnormal	Active Lamp: Amber Count: 1
DTC:197	Coolant level data valid but below normal operating range (moderately severe level)	Inactive Lamp: Amber Count: 1