



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20221025
Creation Date: 2022-10-25



Cummins Vehicle Diagnostic Report

License Plate: MB

Manufacturer: Cummins

Year:

Model:

Sub Model:

Engine:

Path: Cummins>Auto scan>ISB>Live data

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

All parameters

NO.	Name	Value	Units
1	Coolant temperature	192.3	°F
2	Engine oil pressure	55.10	psi
3	Engine speed	2706	rpm
4	Total ECM time (key on time)	12476:04:48	H:M:S