



Shop:
Tel:
Address:

Report ID: MAXIA20221128
Creation Date: 2022-11-28



HD OBD Vehicle Diagnostic Report

License Plate: 25308319-1

Manufacturer: HD OBD

Year:

Model: SAE J1708/J1587,SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>DTC&FFD

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Trouble codes

Codes	Description	Status
SPN 111,FMI 18	Engine coolant level 1 Data valid but below normal operating range - moderately severe level	Engine #1 Active Count : 1
SPN 96,FMI 9	Fuel level 1 Abnormal update rate	Engine #1 Active Count : 1
SPN 3361,FMI 4	Aftertreatment 1 SCR catalyst dosing unit. Voltage below normal, or shorted to low source	Engine #1 Previously Count : 1
SPN 3597,FMI 2	ECU power output supply voltage #1 Data erratic, intermittent or incorrect	Engine #1 Emissions-related Count : 1
SPN 3361,FMI 4	Aftertreatment 1 SCR catalyst dosing unit. Voltage below normal, or shorted to low source	Engine #1 Previously emission- related Count : 1
SPN 3597,FMI 2	ECU power output supply voltage #1 Data erratic, intermittent or incorrect	Engine #1 Permanent Count : 1
SPN 563,FMI 9	Anti-lock braking (ABS) active Abnormal update rate	Transmission #1 Active Count : 2
SPN 751,FMI 11	Transmission primary shift selector. Root cause not known	Transmission #1 Previously Count : 14