



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20221111
Creation Date: 2022-11-11



INTERNATIONAL Vehicle Diagnostic Report

License Plate: PRINCE

Manufacturer: INTERNATIONAL

Year:

Model:

Sub Model:

Engine:

Path: INTERNATIONAL>Automatic selection>Auto scan>SAE J1708/J1587>Live data

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Electronic diesel control -- ALL

NO.	Name	Value	Units
1	Torque limiting factor	100.0	%
2	Two speed axle switch status	High	
3	Road speed	0.00	mph
4	Percent accelerator pedal position	0.8	%
5	Percent engine load	27.5	%
6	Engine oil pressure	38.53	psi
7	Boost pressure	0.38	psi
8	Barometric pressure	14.19	psi
9	Engine coolant temperature	147	°F
10	Exhaust back pressure	6.69	psi
11	Mass air flow	72.125	kg/min
12	Average fuel rate	0.000	gal/s(US)
13	Wheel sensor ABS axle: 1 left	Error	
14	Wheel sensor ABS axle: 2 left	OFF	
15	Wheel sensor ABS axle: 3 left	OFF	



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20221111
Creation Date: 2022-11-11



16	Wheel sensor ABS axle: 1 right	OFF	
17	Wheel sensor ABS axle: 2 right	OFF	
18	Wheel sensor ABS axle: 3 right	OFF	
19	Injection control pressure	493.13	psi
20	Battery potential (voltage)	12.00	V
21	Ambient air temperature	66.5	°F
22	Engine oil temperature	86.8	°F
23	Fuel rate (instantaneous)	0.000	gal/s(US)
24	Engine speed	700	rpm
25	Transmission output shaft speed	0	rpm
26	Total vehicle distance	166283.28	miles