



Shop:
Tel:
Address:

Report ID: MAXIA20230130
Creation Date: 2023-01-30



Cummins Vehicle Diagnostic Report

License Plate: 20PB011

Manufacturer: Cummins

Year:

Model:

Sub Model:

Engine:

Path: Cummins>Control unit>X15 CM2350 X114B/X116B>ECU information

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

ECU information

Marking name	X15 CM2350 X114B/X116B
Engine make	CMMNS
Product ID	BGT
ECM name	CM2350A
ECM code	HD10329.05
ECM S/N	22329231
ECM P/N	4384413
System S/N	80131198
Name	PETERBILT
Vehicle or equipment model	367H
VIN or equipment S/N	1XPBD49X0LD630259
Advertised engine power (hp)	450.2
Advertised engine power rpm (rpm)	1800.0
Peak torque ar rpm (N*m)	2508.0
Peak torque rpm (rpm)	1000.0
Fuel code P/N	0PA57



Shop:
Tel:
Address:

Report ID: MAXIA20230130
Creation Date: 2023-01-30



System model	6X1u17D1500000000
Calibration version	3C461120
Customer name	CUSTOMER
SC option	0
DO option	0
Governed speed (rpm)	1800.0
Engine control parts list	4342
Customer unit number	0000000000
Customer location	