

# DIAGNOSTIC REPORT

VIN: 1HTMMMMNXJH573934

Model Year: 2018

Manufacturer: International

| COMPONENT | FAULT CODES | 1 TOTAL / 0 ACTIVE / 1 INACTIVE |
|-----------|-------------|---------------------------------|
|-----------|-------------|---------------------------------|

|                          |                               |
|--------------------------|-------------------------------|
| <b>ENGINE #1 - J1939</b> | <b>ACTIVE FAULT CODES (0)</b> |
|--------------------------|-------------------------------|

Vehicle Make: Cummins

None

ECM Serial Number: 74111707

ECM Model: 6B u17D0670000000

VIN: 1HTMMMMNXJH573934

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (1)</b> |
|---------------------------------|

Fault Description: Engine Fuel Injection Quantity Error for Multiple Cylinders

SPN 5357

FMI Description: Condition Exists

FMI: 31

Count: 2

|                        |                               |
|------------------------|-------------------------------|
| <b>BRAKES - SYSTEM</b> | <b>ACTIVE FAULT CODES (0)</b> |
|------------------------|-------------------------------|

Vehicle Make: N/A

None

ECM Serial Number: N/A

ECM Model: N/A

VIN: N/A

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (0)</b> |
|---------------------------------|

None

|                                |                               |
|--------------------------------|-------------------------------|
| <b>TRANSMISSION #1 - J1939</b> | <b>ACTIVE FAULT CODES (0)</b> |
|--------------------------------|-------------------------------|

Vehicle Make: N/A

None

ECM Serial Number: N/A

ECM Model: N/A

VIN: N/A

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (0)</b> |
|---------------------------------|

None

|                                |                               |
|--------------------------------|-------------------------------|
| <b>BODY CONTROLLER - J1939</b> | <b>ACTIVE FAULT CODES (0)</b> |
|--------------------------------|-------------------------------|

ECM Serial Number:

None

ECM Model:

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (0)</b> |
|---------------------------------|

None

|                           |                               |
|---------------------------|-------------------------------|
| <b>RETARDER, EXHAUST,</b> | <b>ACTIVE FAULT CODES (0)</b> |
|---------------------------|-------------------------------|

ECM Serial Number:

None

ECM Model:

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (0)</b> |
|---------------------------------|

None

|                                |                               |
|--------------------------------|-------------------------------|
| <b>INSTRUMENT CLUSTER #1 -</b> | <b>ACTIVE FAULT CODES (0)</b> |
|--------------------------------|-------------------------------|

ECM Serial Number:

None

ECM Model:

|                                 |
|---------------------------------|
| <b>INACTIVE FAULT CODES (0)</b> |
|---------------------------------|

None

## PARAMETERS

# DIAGNOSTIC REPORT

VIN: 1HTMMMMNXJH573934

Model Year: 2018

Manufacturer: International

## ENGINE #1 - J1939

|                                   |                  |                                                  |                |
|-----------------------------------|------------------|--------------------------------------------------|----------------|
| Rated Horsepower                  | 249 BHP          | Engine Rated RPM                                 | Not Available  |
| MIL Status                        | Off              | Fuel Level                                       | Not Available  |
| Battery Voltage                   | 12.05 V          | Ignition Voltage                                 | Not Available  |
| Engine RPM                        | 0 RPM            | Vehicle Speed                                    | 0 mph          |
| Throttle Position                 | 0 %              | Brake Switch                                     | N/A            |
| Clutch Switch                     | N/A              | Engine Operating State                           | Engine Stopped |
| Engine Intake Air Temperature     | Not Available    | Engine Intake Air Pressure                       | Not Available  |
| Barometric Pressure               | 14.21 psi        | Coolant Level                                    | 100 %          |
| Coolant Temperature               | 62.6 °F          | Oil Level                                        | Not Available  |
| Oil Temperature                   | Not Available    | Oil Pressure                                     | 0.0 psi        |
| DPF Status                        | Regen not Needed | Regen Status                                     | N/A            |
| DPF Active Regen Inhibited Status | Inhibited        | DPF Active Regen Inhibited Due to Inhibit Switch | Not Inhibited  |
| DPF Regen Inhibit Switch          | N/A              | DPF Regen Force Switch                           | N/A            |
| Exhaust Temperature 1             | 65.6 °F          | Exhaust Temperature 2                            | Not Available  |
| Exhaust Temperature 3             | Not Available    | DPF Intake Temperature                           | 72.7 °F        |
| DPF Outlet Temperature            | 57.0 °F          | DPF Differential Pressure                        | 0 psi          |

## BRAKES - SYSTEM CONTROLLER - J1939

|                  |     |                    |     |
|------------------|-----|--------------------|-----|
| Battery Voltage  | N/A | Ignition Voltage   | N/A |
| Vehicle Speed    | N/A | Brake Switch       | N/A |
| Primary Pressure | N/A | Secondary Pressure | N/A |

## TRANSMISSION #1 - J1939

|                   |               |                    |               |
|-------------------|---------------|--------------------|---------------|
| Battery Voltage   | 12.05 V       | Ignition Voltage   | Not Available |
| Input Shaft Speed | 0 RPM         | Output Shaft Speed | 0 RPM         |
| Oil Level         | Not Available | Oil Life Remaining | N/A           |
| Oil Temperature   | 48.2 °F       | Service Indicator  | N/A           |
| Range Selected    | N/A           | Range Attained     | N/A           |

## LIFE DATA

### ENGINE #1 - J1939

|                                      |              |                                   |            |
|--------------------------------------|--------------|-----------------------------------|------------|
| Distance                             | 278620.27 mi | Hours                             | 7270.90 hr |
| Fuel Used                            | 26809.0 gal  | Average Fuel Economy              | N/A        |
| Engine Idle Hours                    | 635.75 hr    | Engine Idle Fuel Used             | 424.0 gal  |
| PTO Hours                            | N/A          | PTO Fuel Used                     | 36.5 gal   |
| DPF Number of Inhibited Active Regen | N/A          | DPF Number of Manual Active Regen | N/A        |
| DPF Fuel Used                        | N/A          |                                   |            |

DIAGNOSTIC REPORT

VIN: 1HTMMMMNXJH573934  
Model Year: 2018  
Manufacturer: International

TRIP DATA

ENGINE #1 - J1939

|                             |              |                            |             |
|-----------------------------|--------------|----------------------------|-------------|
| Distance                    | 278625.56 mi | Fuel Used                  | 26726.8 gal |
| Average Fuel Rate           | 3.67 gal/hr  | Idle Time                  | N/A         |
| Vehicle Idle Fuel Used      | N/A          | Cruise                     | N/A         |
| Cruise Fuel Used            | N/A          | DPF Active Regen Time      | N/A         |
| DPF Number of Active Regens | N/A          | DPF Used                   | N/A         |
| Vehicle Speed Limit         | 65 mph       | Cruise Control Speed Limit | 65 mph      |