



Impact Track Loader - Pre-Delivery Inspection

Serial No	ASVRT135EPDF00600		
Mbdel No	RT135 Forestry		
Dealer Code			
Dealer Name	Vander Haags		
Dealer Address			
Work Order	201850		
Work Location	Spencer		
Unit Hours			
Dealer Notes			
Date Inspected			

Section Name	Item Name	Result	Comments
Engine Compartment	Check for Radiator Damage	✓	
Engine Compartment	Check for Oil Cooler Damage	✓	
Engine Compartment	Radiator Fluid Level	✓	
Engine Compartment	Fan Guard & Brush Alignment	✓	
Engine Compartment	Fan Belt Tension	✓	
Engine Compartment	Check for Fuel Leaks	✓	
Engine Compartment	Eng. Compartment Fasteners Tight	✓	
Engine Compartment	Air Filter Hose Clamps Tight	✓	
Engine Compartment	Control Valve for Leaks	✓	
Engine Compartment	Hydraulic Oil Level	✓	
Engine Compartment	Hyd Tank & Lines Not Rubbing	✓	
Engine Compartment	Wiring Harness Routing & Tight	✓	
Engine Compartment	Engine Oil Level to Full Mark	✓	
Engine Compartment	Engine Oil Filter Tight	✓	
Engine Compartment	Exhaust System Clamps Tight	✓	
Engine Compartment	Fuel Sediment Bowl Clean	✓	
Engine Compartment	Battery Hold Downs & Cables	✓	
Engine Compartment	Eng. Cover & Screens Condition & Fit	✓	
Undercarriage	Verify Proper Track Tension	✓	
Undercarriage	Axles Have Been Greased	✓	
Undercarriage	Check for leaks around drive motors	✓	
Undercarriage	Hoses Tight and Routed Correct	✓	
Undercarriage	Wheel & Scraper Clearance	✓	
Loader	Check For Leaks	✓	
Loader	Check Hose Routing	✓	
Loader	Test Quick Attach Function	✓	
Loader	Loader pins greased	✓	
Loader	check for loose fasteners	✓	
Loader	Paint free of defects	✓	
Operator environment	Test Track Control Function	✓	
Operator environment	Test Loader Control Function	✓	
Operator environment	Check Float Position	✓	
Operator environment	Test Seat & Lap Bar Safeties	✓	
Operator environment	Test Front & Rear Lights	✓	
Operator environment	Test Dome light	✓	