



Shop: --
Tel: --
Address: --

Email: --

Report ID: MAXIA20230418085050
Test Time: 2023-04-18 08:50:50
Technician: --

EOBD Vehicle Diagnostic Report

Vehicle Information

--/EOBD/SAE J1939/
VIN: --

Odometer Reading: --
License Plate: 25374350

Customer Information

Name: --

Device information

Scanner: MaxiSys MS909CV
Version: V1.10

Serial Number: V19GM5V01572
Repair Order Number:
V19GM5V0157220230418084834037

System Scanned(1)

System	Status/DTC
Engine #1	 1

DTC (1)

Engine #1 (1 DTC)

DTC	Description	Status
SPN 111,FMI 1	Engine coolant level 1 Data valid but below normal operational range - most severe level	Engine #1 Active Count : 11

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.