



Shop:
Tel:
Address:

Report ID: MAXIA20230418
Creation Date: 2023-04-18



HD OBD Vehicle Diagnostic Report

License Plate: 25374350-1

Manufacturer: HD OBD

Year:

Model: SAE J1939

Sub Model:

Engine:

Path: HD OBD>SAE J1939>Vehicle information

Client:

Phone Number:

VIN:

Mileage:

Color:

Status:

Vehicle information

Component identification

Make	CTRPL
Model	C-12
Serial version	2KS82620
Unit number (power unit)	1FUJA6AS93LK44083