Dismantle Sheet

Y4B60

80CH11	3 1980 CH	EVROLET C70	_,_,,,,,,,	C17DBAV135731
		<u>Fluids</u>] .	□ Dismantle R/O Locations upda
		Fuel Engine		Dismantle R/O Locations upda
		Coolant		☐ Chocked Wheels
		Power Steering		☐ Resting on Jack Stands ☐ Cleaned Garbage out of Cab
		Freon		☐ Inspected parts for damage
		Brake Fluid	l č	☐ Mark Frame Rail with Stock #
		Transmission		□ Tag Cores
		Differential(s)		☐ Post Deman Pictures
	Flui	ds Drained by		
Pull Initials		6-1 6-4]	
	Hood Assy	Cnd Status B Available	Location	Tag COMPLETE W/ HEADLAMPS, LESS GRILLE, SEVERAL CRACKS BEL
			yanl	TURN SIGNALS ON EACH VENDER, LH HAS CRACK ON OUTER NEA HINGE, LOWER CENTER OPENING CUT OUT FOR AIR FLOW CHEVROLET C70 SFA RED SINGLE SEALED 39.5
	Radiator	A Available	SOUP	CROSSFLOW W/ RADIATOR CAP CHEVROLET C70 366 24 26 3
	Radiator Overflow Bot	(9)	cab	MOUNTS TO TOP OF RADIATOR CHEVROLET C70 RADIATOR PLASTIC
	Condensor	Not Posted	_	
	Cab	Not Posted	A. S 3 A.	
	Cab Control Module	Not Posted	-	
	Column	A Available	ix	STRAIGHT COLUMN, WHEEL CRACKED CHEVROLET C70 NO MANI
	R Seats	A Available	ge	STATIONARY 60/40 VINYL CHEVROLET C70 SPLIT BENCH VINYL BLACK NO
	Heater Motor	Not Posted		
	Radio	Not Posted	-	
	R Fuel Tanks	A Available		50 GALLON STEEL STEP TANK W/ STRAPS, REAR FILL CHEVROLE C70 50 35 25 15
	Air Tank	Not Posted	1 -	
	Wiper Motor	A Available	ye	WIPER MOTOR ASSEMBLY W/ WASHER, ELECTRIC CHEVROLET C
	Engine Fan	A Available Not Posted	M	366, V8, GAS GM 366 90 Day Parts Only
HH	Starter	Not Posted		Lance of the same
H	Alternator	Not Posted		H
H	Flywheel	Not Posted		
DI.	Steering Pump	A Available	CW-	SINGLE PULLEY P/S PUMP, 366 CHEVY 366
	A/C Compressor	Not Posted	CE	
DI.	Transmission	A Available	12	282V5S W/ DRUM BRAKE, BEHIND 366 V8 CLARK 282V
	Fr Axle	Not Posted		
	Steering Gear	Not Posted	10	
	Fr Leaf Spring(1)	A Available	VG	3", 9 LEAF CHEVROLET C70 3 9 32 22
	Rr Axle(s)	Not Posted	1-	
	Brake Control Module	Not Posted	~	
	Power Divider	Not Posted		
	Carrier	A Available	cl	T170, 2 SPEED, 6.50 RATIO GM T170 6.50 29 NO 3873551
	Axle Shafts(1)	A Available	Cl	GM 29 SPLINE FLOATING AXLE SHAFT 29
Dism	Rr Leaf Spring			PR INTERCHANGE, SEE DAVE PATTON
HH	Fifth Wheel	Not Posted Not Posted	7	
HH	Equipment	Not Posted		
HH	Wheels	Not Posted	77	
H	Front Tires	Not Posted	San	10.00X 20
~			7	10.00X 20
Notes:			***	
	-			

80CH113	1980 CHEVROLET	· C70		C17DBAV135731		
	Rear Tires	Not Posted	1 -	Page 2 of 3		
	Grille	A Available	O'D [CHEVY LOGO, PAINTED, SEVERAL CRACKS CHEVROLET C70		
	Bumper Assembly, Front	A Available	40	PLASTIC INSERT STEEL PAINTED, SEVERAL DENTS NEAR TOW HOOKS CHEVROLET		
	L Tow Hook	A Available	lve [TOW HOOK, BOLT ON CHEVROLET C70		
	R Tow Hook	A Available	he [TOW HOOK, BOLT ON CHEVROLET C70		
TH	L Door Mirror	A Available	/	STAINLESS STEEL, MANUAL CHEVROLET C70 STAINLESS NO NO		
TI	R Door Mirror	A Available	Lyc [STAINLESS STEEL, MANUAL CHEVROLET C70 STAINLESS NO NO		
	Cab Assembly	A Available	vi	CAB SHELL, CLARK 282V5S, COMPONENTS SOLD SEPERATE		
	L Step (Frame, Fuel Tank, Far	A Available	ye [CHEVROLET C70 HYDRAULIC 366 SHELL DOOR ENTRY STEP W/ BRACKETS, RED, SOME SURFACE RUST		
	L Door, Interior Panel	A Available	ye [CHEVROLET C70 42.5 STEEL UNDER DOOR INTERIOR PANEL, SOME SCUFFS W/ ARMREST CHEVROLET C70		
	R Door, Interior Panel	A Available	W [BROWN NO INTERIOR PANEL, SOME SCUFFS, LESS ARMREST CHEVROLET C70 INTERIOR PANEL, SOME SCUFFS, LESS ARMREST CHEVROLET C70		
	L Interior Sun Visor	A Available	90	TAN VINYL INTERIOR SUN VISOR CHEVROLET C70		
TH	R Interior Sun Visor	A Available	1	TAN VINYL INTERIOR SUN VISOR CHEVROLET C70		
	Hub	A Available	1/0	FRONT, CAST# FA92 CHEVROLET C70 DAYTON 5 OUTBOARD FA92		
	Hub	A Available	14	REAR, CAST# 9052B CHEVROLET C70 DAYTON 5 OUTBOARD 9052B		
	Windshield Washer Reservoir	A Available	10	MOUNTS TO CAB CHEVROLET C70 CAB		
	Heater & AC Temperature Co	A Available	11	1 SWITCH 2 SLIDES CHEVROLET C70		

Notes:

Post Dismantle Checklist

All of these items must be completed before a truck is considered finished and a new truck will be brought into the bay for dismantle.

Review Dismantle Sheet before truck goo	es out to yard	
— ALL fluids drained from truck		
ALL batteries/battery cables pulled from	truck	
— ALL parts marked with correct truck num	nber and put on parts cart	
Cab cleaned out, parts being stored in ca	b organized	
ALL driveline pulled and marked with con	rect ujoint type	
Wheels/Tires pulled		
— Fuel and hydraulic tanks pulled		
 Lugnuts/Axlenuts put back on hubs 		
- CRR/PDA bolts put back in housing		
— 5 th wheel inspected		
Scrap cleaned up and thrown away (Iron	and Aluminum)	
ALL parts that need washed moved to wa	ash bay	
Tires dismounted, wheels marked with co	orrect truck number and moved	to wash bay
Parts cart moved to warehouse		
Floor scrubbed and empty parts cart broad	ught out to bay	
Truck Stock Number 80CHU	Dismantler Initials	Supervisor Initials TCS
	Scrap Info	
Stock# 74GM030		
Parts to Pull:	Location:	
•		
•		
•		
Scrap App Completed? (Yes) No (LS		